

平陆县 100MW 农光互补光伏发电项目

监理工程师通知单

编号: ZHJL-JLTZ-PL-061


致: 上海电力安装第一工程有限公司平陆县 100MW 农光互补光伏发电项目 (单位)

主题: 关于东郑光伏场区巡视检查发现以下需要消缺项:


整改内容: 见下图:






11	 12-6-6檩条连接件螺栓未拧紧	12	 12-5-28斜梁弯曲
13	 12-4-5剩余材料在组件下未处理	14	 12-4-5斜撑与斜梁间角度过小
15	 12-5-28桥架下高上低	16	 12-5-28压块倾斜

17	 12-4-14斜梁弯曲	18	 12-5-28標托螺栓未拧
19	 12-5-28胶圈未密封	20	 12-4-14拉杆未安装
21	 12-5-24拉杆未拧紧	22	 12-4-14组件呈台阶状




29	 12-5-24压块缺少螺母	30	 12-4-24组件呈台阶状
31	 12-5-15被拉杆螺母未拧紧	32	 12-4-24剩余压块未处理
33	 12-5-15斜梁弯曲	34	 12-5-6压块缺少弹垫

35	 12-5-15接地未留沉降余地	36	 12-5-6螺栓未按要求预留两到三丝
37	 12-5-15桥架接地断裂	38	 12-5-6背拉杆未安装
39	 12-5-15背拉杆未拧紧	40	 12-5-15压块倾斜

41	 12-5-6斜撑抱箍未拧紧	42	 15-5-15胶圈未密封
43	 12-5-16压块未垂直	44	 12-5-07桥架接地线未连接
45	 12-5-16螺栓未按要求预留两到三丝	46	 15-5-19压块缺少弹垫

47	 12-5-16背拉杆未安装	48	 12-5-7抱箍未拧紧
49	 12-5-23拉杆未安装	50	 12-5-7背拉杆未拧紧
51	 12-5-23斜撑与斜梁间角度过小	52	 12-5-7背拉杆未连接

53	 12-4-23抱箍未拧紧	54	 12-4-23桥架变形，未接地
55	 12-5-23斜梁弯曲	56	 12-4-23胶圈未密封
57	 12-5-23边上桥架连接处 上低下高	58	 12-4-23背拉杆未连接

59	 12-5-28右侧组压块未安装垫片与弹垫	60	 12-4-23背拉杆螺母未拧紧
61	 12-5-28右侧组压块未安装垫片	62	 12-6-7与12-6-22间压块螺母未拧紧
63	 12-4-23斜梁弯曲	64	 12-6-7与12-6-22间立柱安装处无灌注桩

65	 12-4-23压块螺母未拧紧	66	 12-4-23贯穿螺栓生锈
67	 12-6-7檩条连接件螺栓安装错误	68	 12-6-7斜撑与斜梁角度过小
69	 12-6-7螺栓未按要求预留两到三丝	70	 12-6-7拉杆未安装

71	 12-6-7檩托螺栓未安装	72	 12-6-22组件不齐，呈台阶状
73	 12-6-22压块未垂直	74	 12-6-22压块螺母未拧紧
75	 12-6-22檩条弯曲	76	 12-6-22拉杆未安装

77



12-6-22压块未安装弹垫平垫

请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限2个工作日内将整改结果书面回复我方。

项目监理机构（章）：

专业监理工程师：

总监理工程师：

日

期：

2024.5.27



填报说明：本表一式 份，由项目监理机构填写，抄送相关单位。