

平陆县 100MW 农光互补光伏发电项目
监理工程师通知单

编号: ZHJL-JLTZ-PL-134

致: 上海电力安装第一工程有限公司 (总包单位)
抄送: 平陆上电万坤新能源有限公司 (业主单位)
主题:

2024 年 9 月 25 日建设单位、监理单位及总包单位对西沟 6 号地块巡视检查中发现以下问题:
整改内容: 见下图

1



2



3



4



5



6



7



8




9



10



11



060321连接
件未拧
紧。

12



060321压块
未拧紧。

13



060321背拉
杆未拧
紧。

14



060321多于
檩条未裁
剪。

15



现场质量通病。
背拉杆未做好上下交叉。

16



060325压
块倾斜。

17



18




19




20



21



22



23



24



25




26



27



28




29



30



31



32



33



34




35



36



37



38



39



40




41



42




43



44




45



46



47



48



49



50



51



52






53




54



55		56	
57		58	
59		60	

61	 6-4-2接地线未连接	62	 6号箱变围栏未做防腐措施 通病
63	 6-3-6 直流电缆管过密 通病	64	 6-3-6 直流电缆管过密 通病
65	 6-3-20 压块螺丝未紧固 通病	66	 6-3-20 压块螺丝未紧固 通病



以上通病需自查整改，其余地块需同步自查消缺。

请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限 2 个工作日内将整改结果书面回复监理单位。

项目监理机构（章）

专业监理工程师：_____

总监理工程师：平陆县13014170

日

期：_____

填报说明：本表一式 2 份，由项目监理机构填写，抄送相关单位。