

平陆县 100MW 农光互补光伏发电项目

监理工程师通知单

编号: ZHJL-JLTZ-PL-147


致: 上海电力安装第一工程有限公司 (总包单位)

抄送: 平陆上电万坤新能源有限公司 (业主单位)


主题:

2024 年 10 月 28、10 月 29 日建设单位、监理单位及总包单位对东郑 11、10 区光伏区验收过程中发现以下问题:


整改内容: 见下图



5	 11-6-2 撑托缺弹 垫	6	 11-4-22 地埋桩没有 浇筑桩帽
7	 11-6-3 多余压块 拆除	8	 11-4- 23桥架盖 板未清理
9	 11-5- 24对穿螺 栓未安装	10	 11-5- 24压块滑 丝需更换
11	 11-5- 23对穿螺 栓未安装	12	 11-6-3 对穿螺栓 未安装



19	 11-4-9四平方线套管未绑扎	20	 11-4-13拉杆安装不规范
21	 11-4-9缺少对穿螺栓	22	 11-6-18压块受力面小，需要调整
23	 11-6-20斜撑需要调整	24	 11-6-19至11-6-18间接地为连接
25	 11-6-25拉杆需要更换	26	 11-8-5多余压块



33



34



35




36





37




38



39		40	
41		42	
43		44	

45



46



47



48



49



50




51



52



53



54





55




56





65	 10/08/21 5吋管孔塞	66	 10/08/21 5吋管孔塞
67	 10/08/22 斜撑没安装	68	 10/08/22 斜撑不受力 2个
69	 10/08/21 斜撑不受力 2个	70	 10/08/22 缺少对穿

71




72



73



74



75



76



77



78




79




80






81



82



83	 10-06-25斜撑未受力	84	 10-06-29斜撑未受力
85	 10-06-14线前排光伏组件遮挡， 光伏组件周边杂草太多	86	 10-06-05线前排光伏组件 遮挡，周边杂草太多
87	 10/06-02光伏组件损坏破裂	88	 10-1-4前立杆缺少对穿螺栓

89	 10-1-2背拉杆需更换	90	 10-2-13组件装反，需调整	
91	 10号方阵东侧需要清表	92	 10-5-16寒刺遮挡组件	
93	10-4-9, 10-4-10 组串正负极无号码管		94	 10-02-04对穿螺栓有上

请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限 3个 工作日内将整改结果书面回复监理项目部。

项目监理机构（章）：

专业监理工程师：

总监理工程师：

日 期：



填报说明：本表一式 2 份，由项目监理机构填写，抄送相关单位。