

平陆县 100MW 农光互补光伏发电项目

监理工程师通知单

编号: ZHJL-JLTZ-PL-176

致: 上海电力安装第一工程有限公司 (总包单位)

抄送: 平陆上电万坤新能源有限公司 (业主单位)

主题: 2024 年 12 月 28 日、29 日建设单位、监理单位及总包单位在西沟光伏区验收过程中发现以下问题:


整改内容: 见下图

1	 040321 斜撑 不受力。	2	 040325, 两处背拉杆需要交叉固定, 加延长管。
3	 040320, 背 拉杆需加上 延长管。	4	 040324到01, 多 处背拉杆未做好 交叉固定, 整改 需要加长管。

5



6



7



8




9



10



11



040304, 线
缆套管扭
折。

12



040306, 电
缆套管扭
折

13



040306压
块变形。

14



040315, 扎
丝生锈。


15



16



17




18










19



20



21	 4-8-12电缆套管绑扎	22	 4-8-7缺少斜撑
23	 4--8逆变器交流电缆防火泥没封堵	24	 4-1-1缺少元宝垫
25	 4-1-6斜支撑不紧力	26	 4-1-15组件缺失

27		28	
29		30	
31		32	
33		34	
35		36	

37	 4-7-12旁压块未掩埋	38	 4-7-12压块边距不够
39	 4-6-28标识翘起	40	 4-6-2U型螺栓生锈
41	 4-5-21螺丝生锈	42	 4-5-20缺少螺丝
43	 4-5-20标识条连接件处开孔	44	 4-4-14跨接线生锈

45



46



47



48




49



50



51



52



53



54




55



56



57



58



59



60



61



62



63




64



65




66




67



68



69




70




71




72



73



74



75




76



77



78



79



80




81




82



83



84



85



86




87



88



89



90




91



92





93




94



95		96	
97		98	
99		100	


101		102	
103		104	
105		106	
107		108	

109		110	
111		112	
113		114	

115



116



117



118




119




120




121



122



123



124




125



126










127





128



129		130	
131		132	
133		134	

135		136	
137		138	
139		140	

141	 3-6-11环网接地外露	142	 3-7-12环网接地深埋
143	 010607号码管破损。	144	 010607、背拉杆生锈。
145	 040607, 斜拉杆未露丝	146	 0107逆变器防水封堵。
147	 0107逆变器下方电缆没有绑扎固定。	148	 010722套管不够长。

149



150



151



152



153



154




155



156



157



158





159



160



161	 4#箱变8#逆变器电缆管未绑扎 接地未连接接地网 包箍生锈	162	 3-8-22 3-8-28 多余檩条未切割
163	 3-4-4地线接地连接螺 丝生锈	164	 2-5-13四平方电缆需要绑 扎
165	 2-4-11四平方电缆需要绑 扎	166	 2-4-18檩条过长
167	 2-4-3拉杆长度不够，无法 安装双螺母	168	 2-4-5檩托未开孔，缺少螺 栓

169



请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限2个工作日内将整改结果书面回复我方。

项目监理机构（章）

专业监理工程师：

总监理工程师：

日

期：



填报说明：本表一式2份，由项目监理机构填写，抄送相关单位。