

平陆县 100MW 农光互补光伏发电项目

监理工程师通知单

编号: ZHJL-JLTZ-PL-192

致: 上海电力安装第一工程有限公司 (总包单位)



抄送: 平陆上电万坤新能源有限公司 (业主单位)


主题: 2025 年 3 月 23 日建设单位、监理单位及总包单位在洪池地块 29 区、32 区验收过程中发现以下问题:

整改内容: 见下图

1	 32-2-1小弹垫	2	 32-2-1缝隙太大
3	 32-1-27斜槽条弯曲	4	 32-1-25少平少弹少母





5	 32-1-24斜槽条弯曲及撑托调整	6	 32-1-28二次灌胶没做
7	 32-1-28支架没接地线	8	 32-1-28少黄绿线接地
9	 32-2-8螺栓没紧	10	 32-2-17螺栓没紧
11	 32-2-14螺栓没紧	12	 32-2-24螺栓没紧



13		14	
15		16	
17		18	
19		20	

21	 21-1-17缺螺母	22	 21-1-17缺螺母
23	 21-1-23螺栓没紧	24	 21-1-26缺螺母
25	 21-1-25螺栓没紧	26	 21-1-28缺螺栓
27	 21-1-28缺螺栓和螺母	28	 21-1-27螺栓没紧

29	 32-8-6弹垫更换	30	 32-8-5少平弹母
31	 2901逆变器 缺少指示 标牌	32	 290204斜撑 螺栓未拧 紧
33	 290127立 柱生锈	34	 290101斜撑 有破损孔 洞

35	 32-1-21 標条螺栓缺少平垫	36	 32-1-20 標条螺栓缺少彈墊
37	 32-1-19 標条螺栓缺少彈墊	38	 32-1-18 斜撐螺栓未拧紧
39	 32-1-17 抱箍彈墊损坏	40	 32-1-14 標托螺栓未拧紧

41	 32-1-13 檩托未拧紧	42	 32-1-13 檩条螺栓未拧紧
43	 32-1-10 檩托螺栓未拧紧	44	 32-1-9 檩条连接件缺少螺栓
45	 32-1-8 斜梁弯曲	46	 32-1-6 檩托螺栓缺少弹垫

47	 32-1-4 標托未拧紧	48	 32-1-3 標条连接件未拧紧
49	 32-1-10 斜梁標条缺少连接螺栓	50	 32-1-10 斜梁弯曲
51	 32-1-9 斜梁弯曲	52	 32-1-3 斜梁弯曲

53




54



55



56





57






58






59	 32-2-22 左边增补组斜梁弯曲	60	 32-2-21 檩条连接件缺少平垫
61	 32-2-20 抱箍未拧紧	62	 32-2-20 抱箍未拧紧
63	 32-2-20 檩条螺栓缺少弹垫	64	 32-2-19 抱箍未拧紧


65	 32+2-19斜撑未拧紧	66	 32-8-2抱箍弹垫损坏
67	 32-4-19压块间隙多处	68	 32-4-20螺丝松动
69	 32-4-20压块未贴紧	70	 32-4-26压块间隙多处
71	 斜撑抱箍连接处未紧合	72	 32-7-23横托螺丝松动


73	 32-5-29 槽托螺丝少垫片弹 垫未出丝	74	 32-5-22 缺少垫片弹垫
75	 32-5-23 槽托螺丝松动	76	 32-5-16 槽托螺丝松动
77	 32-5-14 螺丝松动	78	 32-5-23 槽托螺丝松动 通病
79	 32-5-2 槽托无螺丝	80	 32-2-26 槽托螺丝未紧


81		82	
83		84	
85		86	
87		88	

89	 32区69号托架缺螺丝	90	 32区69号托架少两颗螺丝
91	 32区69号托架缺螺丝	92	 52区69号托架缺螺丝
93	 32区69号托架缺螺丝	94	 32区逆变器未做标识



95		96	
97		98	
99		100	

101	 29-8后增补 组建斜梁 弯曲	102	 29-8后增补组 件，桩基螺 丝没拧紧。
103	 29-7-1 MC4插头未放 好	104	 29-7-7 左侧增补组串 螺栓未紧固
105	 29-7-4 边压块安装不 到位	106	 29-7-7 左侧增补组串 螺栓未紧固

107	 29-7-6左侧增补组串 檩条连接件缺少螺栓	108	 29-7-10 压块螺栓未 紧固
109	 29-7-11压块螺栓未紧 固	110	 29-7-12 压块螺栓单 螺母
111	 29-7-14 压块螺栓未 安装	112	 29-7-14 檩托螺栓未 紧固
113	 29-7-15 檩条螺栓平 垫生锈	114	 29-7-15边压块螺栓未 紧固


115	 29-7逆变器无标识	116	 29-7逆变器下方mc4 插头未拧紧
117	 29-7-18 压块螺栓单 螺母	118	 29-7-23 压块螺栓未 紧固
119	 29-7-24压块螺栓单螺 母	120	 29-6-5 檩条连接件缺 螺栓
121	 29-5-3压块安装不到 位	122	 29-6逆变器无标识

123		124	
125		126	
127		128	
129		130	

131	 32-3-7 檩条连接件螺栓未上紧	132	 32-3-15 檩条连接处螺栓未上紧
133	 32-3-12 檩条连接处螺栓未上紧	134	 32-3-18 檩条连接处螺栓未上紧
135	 32-3-18 檩条连接处缺少螺栓	136	 32-3-23 檩条连接处螺栓未上紧
137	 32-3-23 压块未上紧	138	 32-3-22 拉杆螺母未上紧

139	 32-3-22 螺栓未上紧	140	 32-3-22 缺少弹垫
141	 32-3-24 檩条连接件螺栓未上紧	142	 32-3-22 压块缺少螺母
143	 32-3-25 檩条连接处螺栓未上紧	144	 32-3-24 檩条连接处螺栓未上紧
145	 32-3-29 斜撑抱箍未上紧	146	 32-3-25 檩条连接处螺栓未上紧

147	 32-4-1 檩条连接件螺栓未上紧	148	 32-3-29 拉杆缺少螺母
149	 32-4-8 檩条连接件螺栓未上紧	150	 32-4-1 檩条连接处螺栓未上紧
151	 32-4-8 拉杆缺少螺母	152	 32-4-8 压块缺少螺母

153	 32-4-7 檩条连接件螺栓未上紧	154	 32-4-7 拉杆缺少螺母
155	 32-4-6 檩条连接件螺栓未上紧	156	 32-4-7 檩条连接处螺栓未上紧
157	 32-4-6 螺栓未上紧	158	 32-4-5 螺栓松动
159	 32-4-6 拉杆缺少螺母	160	 32-4-9 檩托安装不到位

161	 32-4-10 檩条连接处缺少螺栓	162	 32-4-10 檩条连接处缺少垫片
163	 32-4-4 压块缺少螺母	164	 32-4-12 压块缺少螺母
165	 32-4-10 檩条连接处缺少螺栓	166	 32-4-12 檩条连接件缺少垫片
167	 32-4-12 抱箍未上紧		

请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限3个工作日内将整改结果书面回复我方。

项目监理机构（章）

专业监理工程师：

总监理工程师：

日

期：2025.3.24



填报说明：本表一式____份，由项目监理机构填写，抄送相关单位。