

平陆县 100MW 农光互补光伏发电项目
监理工程师通知单

编号: ZHJL-JLTZ-PL-199

致: 上海电力安装第一工程有限公司 (总包单位)

抄送: 平陆上电万坤新能源有限公司 (业主单位)

主题: 2025 年 4 月 15 日监理单位及总包单位在阳朝 25、26、27 地块复验收过程中发现以下问题:

整改内容: 见下图


1



2




3



4



5	 25-1-6 缺少对穿	6	 25-1-6 桥架跨接线断裂
7	 25-1-16 桥架盖板未关闭 (通病)	8	 25-1-16 桥架盖板螺栓未紧
9	 25-1-20 缺少斜撑	10	 25-1-28 缺少斜撑 (与之前一样)

11		12	
13		14	
15		16	

17



18



19




20




21



22



23	 27-10-8左上角组件接 地线未连接	24	 27-10-5u型螺栓单螺 母
25	 27-10-12 u型螺栓单 螺母	26	 27-10-12 缺少斜撑
27	 27-10-13 檩条连接件 缺少螺栓	28	 27-10-13 u型螺栓单 螺母 缺弹、平垫
29	 27-10-13 压块与组件 缝隙过大	30	 25-1逆变器处横梁 防火封堵破损

31		32	
33		34	
35		36	
37		38	


39



40



41



42



43



请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限3个工作日内将整改结果书面回复我方。



项目监理单位（章）：

专业监理工程师： 王学全

总监理工程师： 高红梅

日期： 2025.4.15

填报说明：本表一式 份，由项目监理单位填写，抄送相关单位。