



平陆县 100MW 农光互补光伏发电项目

监理工程师通知单

编号: ZHJL-JLTZ-PL-133

致: 上海电力安装第一工程有限公司 (总包单位)
抄送: 平陆上电万坤新能源有限公司 (业主单位)
主题:

2024 年 9 月 24 日建设单位、监理单位及总包单位对阳朝 23 区巡视检查中发现以下问题:
整改内容: 见下图

1	 23—2—16 缺斜撑, 缺拉杆	2	 23—2—3剖 开套管需绑扎 及俩头未绑扎 牢固
3	 没有斜撑 及更换斜 撑 23—2—7	4	 230210标签悬空.


5



6



7



8



9



10




11



230201压
块倾斜。

12



230201压
块倾斜。

13



230129连接
件未拧
紧。

14



230129背拉杆螺
丝未拧紧。

15




230129檩条悬空。

16



230128斜拉
杆生锈。

17



18




19



20



21



22



23



230120斜拉杆生锈。

24



230106檩条悬空。

25



230105压块倾斜。

26




230105支架倾斜。

27



23-1-24卡块未靠死

28



23-1-2 立柱固定螺栓缺少 漏装

29 23-1-2 边压块安装不垂直 通病	30 23-1-16 压块安装未贴合组件 通病
31 23-1-2 直流电缆敷设测试 通病	

以上通病需自查整改，其余地块需同步自查消缺。

请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限 2 个 工作日内将整改结果书面回复监理项目部。

项目监理机构（章）

专业监理工程师： 王芳金

总监理工程师： 高林

日 期： 2024.7.24

填报说明：本表一式 2 份，由项目监理机构填写，抄送相关单位。