

平陆县 100MW 农光互补光伏发电项目
监理工程师通知单


编号: ZHJL-JLTZ-PL-190


致: 上海电力安装第一工程有限公司 (总包单位)

抄送: 平陆上电万坤新能源有限公司 (业主单位)


主题: 2025 年 3 月 22 日建设单位、监理单位及总包单位在新西沟地块 33 区验收过程中发现以下问题:


整改内容: 见下图


1		2	
3		4	
5		6	


7		8	
9		10	
11		12	
13		14	



15		16	
17		18	
19		20	

21	 33-4-16缺少两个对穿螺栓	22	 33-4-1缺少两个对穿螺栓
23	 33-4-1缺少对穿螺栓	24	 33-4-3缺少对穿螺栓
25	 33-4-5檩条连接件缺少弹垫	26	 33-4-19缺少对穿螺栓
27	 33-3-2电缆敷设不规范	28	 33-3-8需要更换长拉杆


29	 33-3-3 电缆敷设不规范	30	 33-3-12 压块与组件间隙大
31	 33-3-8 电缆敷设不规范	32	 33-3-17 压块缺少螺母
33	 33-3-17 压块组件间有间隙	34	 33-3-17 mc4 插头未固定
35	 33-3-19 压块垫片错位	36	 33-3-17 四平方电缆敷设不到位

37	 33-3-20mc4插头未固定	38	 33-3-24mc4插头未固定
39	 33-6-36多个压块螺丝固定	40	 33-6-22缺对穿螺丝
41	 33-5-21缺对穿螺丝	42	 33-6-17缺对穿螺丝
43	 33-8-21 1个压块一块压板未固定	44	 33-6-15缺对穿螺丝


45		46	
47		48	
49		50	
51		52	

53		54	
55		56	
57		58	
59		60	

61




62



63



64



65



66



67



68



请贵单位按照上述问题立即消缺整改。

请贵单位在收到本通知后进行立即整改，限3个工作日内将整改结果书面回复我方。

项目监理单位（章）：

专业监理工程师：

总监理工程师：

日

期：



填报说明：本表一式 份，由项目监理单位填写，抄送相关单位。