

监理工程师通知回复单

工程名称：平陆县 100MW 农光互补光伏发电项目

编号：SPEC-JLTZHF-PL-162

致：常州正衡电力工程监理有限公司平陆县 100MW 农光互补光伏发电项目监理项目部：

我方接到编号为 ZHJL-JLTZ-PL-162 的监理工程师通知后，已按要求完成了相关整改工作，现报上，
请予以复查。

详细内容见附件

施工单位（章）

项目经理：

日期：2024 年 12 月 09 日

检查结果：

已整改完成

监理单位（章）

专业监理工程师：

总监理工程师：

日期：2024 年 12 月 09 日

本表一式二份，由项目施工单位填写，项目监理机构、施工单位各 1 份。

1954年10月



整改照片



(1) 31-5-2 已下调



(2) 31-5-17 已下调



(3) 31-5-5 已下调




(4) 31-7-8 已下调



(5) 31-7-9 已下调



(6) 31-4-27 已下调



(7) 31-7-10 已下调




(8) 31-3-24 已下调



(9) 31-2-27 已下调




(10) 31-3-26 已下调




(11) 31-3-28 已下调



(12) 31-2-23 已下调



(13) 31-2-21 已下调



(14) 31-2-19 已下调



(15) 31-4-2 已下调



(16) 31-2-20 已下调



(17) 31-05-09 螺母已加



(18) 31-05-09 螺母已加



(19) 31-05-16 螺母已加



(20) 31-05-05 螺母已加



(21) 31-05-05 螺母已加



(22) 31-05-04 螺母已加



(23) 31-3-21 螺母已加



(24) 31-2-19 螺母已加



(25) 31-3-16 螺母已加



(26) 31-3-15 已下调



(27) 31-3-15 已下调



(28) 31-03-09 立柱下调



(29) 31-04-21 (螺丝已调整)



(30) 31-4-13 已加螺母



(31) 31-2-25 螺母已加




(32) 32-2-23 螺母已加



(33) 31-4-6 螺丝调整



(34) 31-4-2 螺丝调整



(35) 31-3-23 螺母已加



(36) 31-3-24 螺丝调整



(37) 31-3-26 螺母已加



(38) 31-3-28 螺母已加



(39) 31-2-19 螺母已加



(40) 31-2-08 组件角度调整



(41) 31-2-08 角度调整



(42) 31-4-25 立柱调整



(43) 31-5-27 立柱角度调整