

GFDZJBM30: 旁站监理记录表

旁站监理记录表

工程名称：山东寿光农产品物流园屋顶 30MWp 光伏发电项目

编号: 017

日期及天气: 2007.5.30 31℃ 16%		施工单位: 泰和大道																										
旁站监理的部位或工序: 16开之板墙(02)及新架(ZGSB11-G-1250/35)																												
旁站监理开始时间: 15:30	旁站监理结束时间: 17:10																											
旁站的关键部位、关键工序施工情况:																												
试合16开板墙 安全距离措施规范, 组内(10)管理, 人员配备齐全, 专人负责, 专人负责并确认(10)设施完善。 试合16开板墙 (ME4000B) - 直落(10)测试 (ME2RC-20A) 试合16开板墙 (ME4000B) 已在安全距离内。 试合16开板墙直落(10)测试: <table border="1"> <thead> <tr> <th>I</th> <th>AB-12.62</th> <th>BC-12.65</th> <th>CA-12.62</th> </tr> </thead> <tbody> <tr> <td>II</td> <td>AB-12.41</td> <td>BC-12.44</td> <td>CA-12.42</td> </tr> <tr> <td>III</td> <td>AB-12.00</td> <td>BC-11.99</td> <td>CA-12.01</td> </tr> <tr> <td>IV</td> <td>AB-11.59</td> <td>BC-11.59</td> <td>CA-11.57</td> </tr> <tr> <td>V</td> <td>AB-11.38</td> <td>BC-11.38</td> <td>CA-11.39</td> </tr> </tbody> </table> 试合16开板墙直落(10)测试: m2 <table border="1"> <thead> <tr> <th>ab-1.491</th> <th>bc-1.486</th> <th>ca-1.488</th> </tr> </thead> <tbody> <tr> <td>ab-1.491</td> <td>bc-1.486</td> <td>ca-1.488</td> </tr> </tbody> </table> 试合16开板墙直落(10)测试: 100G2, 试合16开板墙 68kV, 试合16开板墙 1min 试合16开板墙直落(10)测试: >100G2, 试合16开板墙 25kV, 试合16开板墙 1min			I	AB-12.62	BC-12.65	CA-12.62	II	AB-12.41	BC-12.44	CA-12.42	III	AB-12.00	BC-11.99	CA-12.01	IV	AB-11.59	BC-11.59	CA-11.57	V	AB-11.38	BC-11.38	CA-11.39	ab-1.491	bc-1.486	ca-1.488	ab-1.491	bc-1.486	ca-1.488
I	AB-12.62	BC-12.65	CA-12.62																									
II	AB-12.41	BC-12.44	CA-12.42																									
III	AB-12.00	BC-11.99	CA-12.01																									
IV	AB-11.59	BC-11.59	CA-11.57																									
V	AB-11.38	BC-11.38	CA-11.39																									
ab-1.491	bc-1.486	ca-1.488																										
ab-1.491	bc-1.486	ca-1.488																										
发现的问题及处理情况:																												
无																												
旁站监理人员 (签字): 2007年5月30日																												

- 注 1. 本表由监理工作人员填写。监理项目部可根据工程实际情况在策划阶段对“旁站的关键部位、关键工序施工情况”进行细化,可细化成有固定内容的填空或判断填写方式,方便现场操作。但表格整体格式不得变动。
2. 如监理人员发现问题性质严重,应在记录旁站监理表后,发出监理工程师通知单要求施工项目部进行整改。
3. 本表一式一份,监理项目部留存。